

FIGURE B3a
 SITE PHOTOGRAPHS
 NEWLY IDENTIFIED ISSUES



2. 597 New South Head Road Garage below road



3. 5 Cranbrook Road Floor below road



9. 10 Cranbrook Road Floor below road, Garage below road, Road and footpath graded towards residence



10. 18 Cranbrook Road Garage below road



11. 20 Cranbrook Road Floor below road, Garage below road, Road and footpath graded towards residence



12. 22 Cranbrook Road Floor below road, Garage below road, Road and footpath graded towards residence



13. 621 New South Head Road Garage below road



14. 623 New South Head Road Garage below road



16. 635 New South Head Road Floor below road



17. 59 O'Sullivan Road Garage below road



26. 71 O'Sullivan Road Floor below road, Garage below road



27. 69 O'Sullivan Road Garage below road



28. 2 Powell Road Floor below road



29. 4 Powell Road Floor below road



30. 9 Balfour Road Floor below road



31. 11 Balfour Road Floor below road

FIGURE B3b
 SITE PHOTOGRAPHS
 NEWLY IDENTIFIED ISSUES



32. 13 Balfour Road Floor below road



37. 18 Balfour Road Garage below road



39. 23 Beresford Road Floor below road, Road and footpath graded towards residence



41. 37 Salisbury Road Garage below road



43. 4 Beresford Crescent Floor below road, Garage below road, Ponding on street, Flooding due to overland flow from road above property



48. 7 Beresford Crescent Garage below road



49. 44 Cranbrook Road Floor below road, Garage below road, Road and footpath graded towards residence



50. 46 Cranbrook Road Floor below road, Garage below road, Road and footpath graded towards residence



51. 48 Cranbrook Road Floor below road, Garage below road, Road and footpath graded towards residence



52. 8 Carrington Avenue Floor below road, Garage below road



56. 2 Drimalbyn Road Floor below road



57. 6 Drimalbyn Road Garage below road



62. 34 Drimalbyn Road Floor below road, Garage below road



63. 46 Drimalbyn Road Floor below road, Garage below road



64. 48 Drimalbyn Road Floor below road, Garage below road



65. 50 Drimalbyn Road Floor below road, Garage below road

FIGURE B3c
SITE PHOTOGRAPHS
NEWLY IDENTIFIED ISSUES



66. 52 Drumalbyn Road Floor below road



67. 54 Drumalbyn Road Floor below road, Garage below road



68. 47 Beresford Road Floor below road, Garage below road, Road and footpath graded towards residence, Flow diversion



69. 45 Beresford Road Floor below road, Road and footpath graded towards residence, Flow diversion



70. 6 Plumer Road Floor below road, Yard flooding



72. 52 Salisbury Road Floor below road, Garage below road, Main flow channel bordering residence



73. 54 Salisbury Road Floor below road, Garage below road, Main flow channel bordering residence



74. 56 Salisbury Road Floor below road, Garage below road, Main flow channel bordering residence



77. 64 Salisbury Road Floor below road, Yard flooding, Main flow channel bordering residence



79. 70 Salisbury Road Floor below road, Garage below road, Main flow channel bordering residence



82. 76 Salisbury Road Floor below road, Garage below road, Main flow channel bordering residence



83. 78 Salisbury Road Floor below road, Garage below road, Main flow channel bordering residence

FIGURE B3d
SITE PHOTOGRAPHS
NEWLY IDENTIFIED ISSUES



84. 80 Salisbury Road Floor below road, Garage below road, Main flow channel bordering residence



85. 63 Beresford Road Floor below road, Garage below road, Main flow channel bordering residence



87. 65 Beresford Road Floor below road, Garage below road, Main flow channel bordering residence



89. 71 Beresford Road Garage below road, Main flow channel bordering residence



90. 73 Beresford Road Floor below road, Garage below road, Main flow channel bordering residence



94. 88 Balfour Road Garage below road



95. 90 Balfour Road Garage below road



96. 79 Beresford Road Floor below road, Garage below road, Main flow channel bordering residence



97. 94 Balfour Road Floor below road, Flooding due to overland flow from road above property



98. 81 Beresford Road Floor below road



100. 85 Beresford Road Floor below road



101. 100 Balfour Road Floor below road, Yard flooding



103. 106 Balfour Road Floor below road, Yard flooding



104. 66 Drumalbyn Road Floor below road, Garage below road, Flow diversion



105. 110 Balfour Road Garage below road



106. 112 Balfour Road Floor below road, Garage below road

FIGURE B3e
SITE PHOTOGRAPHS
NEWLY IDENTIFIED ISSUES



107. 84 Drumalbyn Road Floor below road, Garage below road, Road and footpath graded towards residence



108. 88 Drumalbyn Road Floor below road, Garage below road, Ponding on street



109. 90 Drumalbyn Road Floor below road, Garage below road, Ponding on street



110. 89 O'Sullivan Road Floor below road



111. 95 O'Sullivan Road Garage below road



112. 35 Balfour Road Floor below road, Garage below road



113. 41 Balfour Road Floor below road, Garage below road, Main flow channel bordering residence



114. 43A Balfour Road Floor below road, Garage below road, Main flow channel bordering residence



115. 43 Balfour Road Floor below road, Garage below road, Main flow channel bordering residence



116. 45 Balfour Road Floor below road, Garage below road, Main flow channel bordering residence



117. 47 Balfour Road Floor below road, Garage below road, Main flow channel bordering residence




119. 51 Balfour Road Floor below road, Garage below road, Main flow channel bordering residence



120. 11 Latimer Road Garage below road, Road and footpath graded towards residence



121. 73 Balfour Road Garage below road, Main flow channel bordering residence



123. 27 Latimer Road Floor below road, Garage below road, Main flow channel bordering residence



124. 77 Balfour Road Garage below road

FIGURE B3f
SITE PHOTOGRAPHS
NEWLY IDENTIFIED ISSUES



125. 29 Latimer Road Floor below road, Garage below road, Main flow channel bordering residence



126. 31 Latimer Road Floor below road, Garage below road, Main flow channel bordering residence



127. 33 Latimer Road Floor below road, Garage below road, Main flow channel bordering residence



128. 35 Latimer Road Garage below road, Main flow channel bordering residence



130. 75 Victoria Road Floor below road, Garage below road, Yard flooding



131. 77 Victoria Road Floor below road



132. 81 Victoria Road Floor below road, Garage below road, Yard flooding



133. 85A Victoria Road Floor below road, Garage below road, Yard flooding



134. 41 Drumalbyn Road Garage below road



135. 43 Drumalbyn Road Garage below road



136. 49 Drumalbyn Road Garage below road, Ponding on street



137. 125A Victoria Road Floor below road, Ponding on street



138. 87 Drumalbyn Road Garage below road



139. 127 Victoria Road Ponding on street, High velocity flow, No flow path



140. 95 Drumalbyn Road Garage below road, Yard flooding



141. 20 Latimer Road Floor below road, Garage below road, Main flow channel bordering residence

FIGURE B3g
 SITE PHOTOGRAPHS
 NEWLY IDENTIFIED ISSUES



143. 155 O'Sullivan Road Garage below road



144. 169 O'Sullivan Road Floor below road, Flooding due to overland flow from road above property



145. 171 O'Sullivan Road Flooding due to overland flow path from adjacent street



146. 173 O'Sullivan Road Flooding due to overland flow path from adjacent street



147. 175 O'Sullivan Road Flooding due to overland flow path from adjacent street



150. 181 O'Sullivan Road Flooding due to overland flow path from adjacent street



152. 45 Bunyula Road Floor below road



153. 43 Bunyula Road Floor below road



154. 33 Boronia Road Floor below road



156. 45 Boronia Road Floor below road, Ponding on street, Flooding due to overland flow from road above property



157. 47 Boronia Road Floor below road, Ponding on street, Flooding due to overland flow from road above property



161. 55 Boronia Road Flooding due to overland flow from road above property



162. 64 Boronia Road Flooding due to overland flow path from adjacent street



163. 62 Boronia Road Flooding due to overland flow path from adjacent street



166. 13 Bunyula Road Floor below road, Ponding on street, No flow path, Flooding due to overland flow from road above property



167. 15 Bunyula Road Floor below road, Ponding on street, No flow path, Flooding due to overland flow from road above property

FIGURE B3h
SITE PHOTOGRAPHS
NEWLY IDENTIFIED ISSUES



168. 17 Bunyula Road Floor below road, Ponding on street, No flow path, Flooding due to overland flow from road above property



174. 19 Bundarra Road Floor below road, Garage below road



175. 17 Bundarra Road Floor below road, Garage below road



176. 15 Bundarra Road Floor below road, Garage below road, Ponding on street, Flooding due to overland flow from road



179. 9 Bundarra Road Floor below road, Garage below road, Ponding on street



180. 7 Bundarra Road Floor below road, Garage below road, Ponding on street



186. 223 O'Sullivan Road Garage below road, Flow diversion



187. 229 O'Sullivan Road Garage below road



188. 31B Blaxland Road Floor below road



189. 29 Blaxland Road Floor below road



190. 27 Blaxland Road Floor below road, Garage below road



191. 25 Blaxland Road Floor below road



192. 23 Blaxland Road Floor below road



194. 80 Birriga Road Floor below road, Garage below road, Road and footpath graded towards residence, Main flow channel bordering residence



195. 88 Birriga Road Floor below road, Garage below road, Road and footpath graded towards residence, Main flow channel bordering residence



197. 94A Birriga Road Floor below road, Main flow channel bordering residence

FIGURE B3i
SITE PHOTOGRAPHS
NEWLY IDENTIFIED ISSUES



200. 255 O'Sullivan Road Garage below road



201. 247 O'Sullivan Road Floor below road, Garage below road



203. 239 O'Sullivan Road Garage below road



204. 4 Bundarra Road Flooding due to overland flow path from adjacent street



206. 73 Birriga Road Floor below road, Road and footpath graded towards residence



207. 23 Birriga Road Garage below road, Road and footpath graded towards residence, Main flow channel bordering residence



208. 21 Birriga Road Garage below road, Road and footpath graded towards residence, Main flow channel bordering residence



209. 19 Birriga Road Garage below road, Road and footpath graded towards residence, Main flow channel bordering residence



210. 17 Birriga Road Garage below road, Flooding due to overland flow from road, Road and footpath graded towards residence



211. 2 Banksia Road Garage below road, Road and footpath graded towards residence



212. 4 Banksia Road Floor below road, Road and footpath graded towards residence



213. 194 Old South Head Road Floor below road, Flooding due to overland flow from road above property



214. 202 Old South Head Road Garage below road



215. 242 Old South Head Road Garage below road



216. 244 Old South Head Road Garage below road



218. 278 Old South Head Road Floor below road, Road / footpath graded towards residence, Flooding from road, overland flow

FIGURE B3j
 SITE PHOTOGRAPHS
 NEWLY IDENTIFIED ISSUES



224. 4 Albemarle Avenue Garage below road



226. 9 Wilberforce Avenue Garage below road



229. 12 Richmond Road Floor below road



230. 10 Richmond Road Floor below road



231. 6 Richmond Road Floor below road



232. 614 New South Head Road Floor below road, Ponding on street



234. 19 Collins Avenue Garage below road



235. 17 Collins Avenue Garage below road



237. 710 New South Head Road Floor below road



238. 2 Caledonian Road Floor below road



239. 740 New South Head Road Floor below road



240. 748 New South Head Road Floor below road



241. 750 New South Head Road Floor below road



242. 762 New South Head Road Garage below road



243. 774 New South Head Road Floor below road



244. 776 New South Head Road Floor below road, Garage below road

FIGURE B3k
SITE PHOTOGRAPHS
NEWLY IDENTIFIED ISSUES



245. 780 New South Head Road Floor below road



246. 788 New South Head Road Floor below road



247. 6 Tivoli Avenue Floor below road, Ponding on street



249. 46 Towns Road Garage below road



250. 36 Chamberlain Avenue Floor below road, Garage below road, Flooding due to overland flow path from adjacent street



251. 2 Rawson Road Flooding due to overland flow from road above property



252. 34 Chamberlain Avenue Garage below road, Flooding due to overland flow from road above property



253. 36 Chamberlain Avenue Floor below road, Garage below road, Flooding due to overland flow from road above property



254. 16 Old South Head Road Garage below road



255. 692 Old South Head Road Floor below road



256. 37 Dudley Road Flooding due to overland flow path from adjacent street



257. 35 Dudley Road Flooding due to overland flow path from adjacent street



258. 35 Dudley Street Floor below road, Flow diversion



260. 12 Mitchell Road Flooding due to overland flow from road above property



260. 29 Ebsworth Road Floor below road, Main flow channel bordering residence



263. 27 Ebsworth Road Floor below road, Main flow channel bordering residence

FIGURE B3I
 SITE PHOTOGRAPHS
 NEWLY IDENTIFIED ISSUES



285. 19 Fernleigh Avenue Garage below road



309. 554 Old South Head Road Floor below road



310. 566 Old South Head Road Garage below road



311. 570 Old South Head Road Garage below road



312. 586 Old South Head Road Garage below road



313. 7 Hamilton Street Floor below road, Garage below road, Flooding due to overland flow from road above property



314. 11 Hamilton Street Floor below road, Garage below road, Flooding due to overland flow path from adjacent street



315. 15 Hamilton Street Floor below road, Flooding due to overland flow path from adjacent street



319. 38 Dover Road Flooding due to overland flow from road above property, Ponding on street



320. 40 Dover Road Garage below road, Flooding due to overland flow from road above property, Ponding on street



321. 532 Old South Head Road Floor below road



322. 520 Old South Head Road Floor below road



323. 69 Dover Road Garage below road, Ponding on street



324. 65 Dover Road Garage below road, Ponding on street



334. 44 Wilberforce Avenue Garage below road